

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2021

Submitted Date:

10/10/2021

Document Number:

696105130

FIELD INSPECTION FORMLoc ID 448376 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448373	WELL	PR	07/01/2020	OW	123-43873	Wells Ranch State AA33-750	PR
448374	WELL	PR	07/01/2020	OW	123-43874	Wells Ranch State AA33-755	PR
448381	WELL	PR	07/01/2020	OW	123-43878	Wells Ranch State AA33-744	PR

General Comment:

This is a WELL inspection.
Well(s): 3: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID (480892).
Centralized Battery serves 3 Location IDs (448379, 448376, 448378).
(Well(s): 10: Producing | PR).

Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	Methanol, Corrosion Inhibitor.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	3: Wellsites.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	3: Wellsites. Iron panel.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas lift manifold. Iron pipe.		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	3: Wellsites.		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	3: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	3: Wellsites. Gas lift injection lines.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	1: Corrosion Inhibitor pump, tank w/ drip containment. Placards. 1: Methanol pump, tank w/ drip containment. Placards.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	3: Gas lift allocation meters. Calibration cards indicate calibration within last year. Last calibration: 08/11/2021. Active.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.466436,-104.436071
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (480892). Centralized Battery serves 3 Location IDs (448379, 448376, 448378). Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 448373 Type: WELL API Number: 123-43873 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 448374 Type: WELL API Number: 123-43874 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/28/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 448381 Type: WELL API Number: 123-43878 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 10/05/2021 at approximately 17:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Wells Ranch State /AA33-755 Pad Location ID: 448376 Well Name(s): Wells Ranch State AA33-750, Wells Ranch State AA33-755, Wells Ranch State AA33-744. API: 05-123-43873, 05-123-43874, 05-123-43878. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 3: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (480892). Centralized Battery serves 3 Location IDs (448379, 448376, 448378). (Well(s): 10: Producing PR).</p> <p>Refer to Field Inspection Report doc. #696105125 and/or Facility ID #480892 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/10/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105131	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5550902