

Inspection Photos

10/08/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 311604

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311604



Photo 1: Photos shows electrical box and wires observed on the north end of the Location; wires observed to be disconnected, exposed and laying on the surface; equipment is unused.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311604



Photo 2: Photos taken from the separator equipment. Photos show wildlife protection screen has been installed on the northern separator, however, screen was not observed on the southern separator (arrow)



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311604



Photo 3: Photo provides examples of noxious weeds (Houndstongue, Plumeless thistle) observed on the interim areas of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311604



October 8, 2021
39.43910716N 107.81199488W

Photo 4: Photo shows fence around rocks on the southern interim areas of the Location is in disrepair.

