

Inspection Photos
Location Name: Evans Federal 43-28
Location ID: 313158



Photo 1. Overview of location taken facing west. Annual weeds drying on location.




Photo 2. No bradenhead access apparent.

