

Inspection Photos

API: 071-08083

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021

Inspection Photos



Photo 1. Facing southeast along the main access road. The black poly line remains exposed to potential damage. The culvert shown at red arrow is filled in with sediment on the opposite side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021

Inspection Photos



Photo 2. The damaged culverts need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021

Inspection Photos



Photo 3. Facing southwest along the main road. There is a culvert installed for temporary passage. An engineered size culvert will be needed along with bank and inlet/outlet protection. Previous corrective action was not completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021

Inspection Photos



Photo 4. There is a produced water line that is bent over on the ground near the stream drainage which needs to be repaired. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021

Inspection Photos



Photo 5. The cement culvert is filled in with sediment. The culvert at red arrow is not sufficient as shown by the size of the previous culvert. The liner debris in lower portion of photo needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021

Inspection Photos



Photo 6. Facing back to the northeast at the stream crossing further along the road. This area of the road needs to be stabilized with gravel as well as bank stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021

Inspection Photos



Photo 7. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 10/12/2021