

Inspection Photos
Location Name: Cottonwood Gulch Federal C-1
Location ID: 312960



Photo 1. Overview of location taken facing northwest.



Inspection Photos
Location Name: Cottonwood Gulch Federal C-1
Location ID: 312960




Photo 2. No bradenhead access apparent.



Photo 3. Animal burrows compromising berm.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources