

Inspection Photos
Location Name: Cottonwood Gulch State A 1
Location ID: 312957



Photo 1. Overview of location taken facing southeast.

Inspection Photos
Location Name: Cottonwood Gulch State A 1
Location ID: 312957



Photo 2. No bradenhead access apparent.



Photo 3. 2 emergency numbers on tank label.



Inspection Photos
Location Name: Cottonwood Gulch State A 1
Location ID: 312957



Photo 4. Annual weeds and sediment migration on access road.



Photo 5. Annual weeds and sediment migration on access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources