

**Inspection Photos**  
**Location Name: Handke 1**  
**Location ID: 320115**



**Pic 1 tanks**



**Pic 2 stained soil near load out line.**

**Inspection Photos**  
**Location Name: Handke 1**  
**Location ID: 320115**

Oct 14, 2021 at 2:29:03 PM  
39.800479,-104.527072  
800-7102 N Manilla Rd  
Bennett CO 80102  
United States  
COGCC



**Pic 3 tanks weeds unmanaged on location**

Oct 14, 2021 at 2:29:46 PM  
39.800696,-104.527316  
801-7103 N Manilla Rd  
Bennett CO 80102  
United States  
COGCC



**Pic 4 open top tank unable to inspect due to weeds.**



**Inspection Photos**  
**Location Name: Handke 1**  
**Location ID: 320115**




**Pic 5 vertical Separator weeds unmanaged, unable to inspect inside of separator house due to weed growth**



**Pic 6 Horizontal separators, weeds unmanaged.**



**Inspection Photos**  
**Location Name: Handke 1**  
**Location ID: 320115**



**Pic 7 mechanical issue, stained soil on horizontal separator**



**Pic 8 wellhead weeds unmanaged.**