

Inspection Photos

10/13/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334270

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334270



October 13, 2021
39.41472828N 107.72134517W



October 13, 2021
39.41473295N 107.72139564W

Photo 1: Photos 1-2 provide an overview from the south end of the Location facing east, southeast, southwest to west.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334270



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334270



Photo 3: Photos provide example of vegetation observed on the southern and northern areas of the Location; Vegetation observed in these areas are predominantly weedy plant species, though desirable plant establishment beneath the weeds is evident; additional time likely required for desirable plants to outcompete weeds.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334270



October 13, 2021
39.41434675N 107.720156W



October 13, 2021
39.41434585N 107.72013677W

Photo 4: Photo provides example of vegetation observed within the central areas of the Location; vegetation observed is progressing towards 1004 revegetation standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334270



Photo 5: Photo taken from the east end of the Location, facing east. Photo shows a cut/exposed pipe left on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334270



October 13, 2021
39.41478363N 107.72010716W

Photo 6: Continued from photos 5. Photo shows pipeline traveling east from the Location.