

# Inspection Photos

10/13/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 414530

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 414530



**Photo 1:** Photos 1-2 provide an overview from the west end of the Location facing north, northeast, southeast to south.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 414530



October 13, 2021  
39.40938268N 107.71266953W



October 13, 2021  
39.40939148N 107.712661W

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 414530



**Photo 3:** Photo taken from north end of the Location. Photo of the soil stockpile. Soil stockpile predominantly bare and exposed soil; reclamation/revegetation not progressing towards 1003 standards. Erosion degradation and bindweed establishment observed

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 414530



**Photo 4:** See comments under photo 3.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 414530



**Photo 5:** Photo provides example of remnant bindweed from the 2021 growing season observed on the soil stockpile.