

Inspection Photos

10/13/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334283

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334283



Photo 1: Photos taken from the southwestern interim areas of the Location. Though desirable vegetation is evident, photo shows vegetation is predominantly undesirable weedy plant species. Additional reclamation likely necessary for site to meet 1003 standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334283



Photo 2: Photos taken from the northwest end of the Location. Photos provide an overview of the Location from east to southeast.