

Inspection Photos
Operator: Simcoe
API: 067-08790
Date: 10/13/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and smooth brome.




Photo 3. View of Russian knapweeds interspersed within the southern cut-slope area. Approx. 75 individuals observed.



Photo 4. View of reference area comprised of irrigated grass fields mixed with irrigated grasses such as smooth brome and red fescue, as well as wetland vegetation such as cattails, sedges, rushes, and foxtail barley.