

Inspection Photos
Operator: Simcoe
API: 067-09513
Date: 10/13/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern project area facing eastward. Revegetation is progressing with smooth brome, intermediate wheatgrass, sand dropseed, and crested wheatgrass.



Photo 3. View of the southern cut-slope from the southwestern corner facing eastward.



Photo 3. View of Russian knapweeds interspersed within the southern cut-slope area. Approx. 75 individuals observed.



Photo 4. View of reference area comprised of irrigated grass fields mixed with irrigated grasses such as smooth brome and red fescue, as well as wetland vegetation such as cattails, sedges, rushes, and foxtail barley.