

Inspection Photos

10/18/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311696

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 311696



October 18, 2021
39.52423218N 107.65922672W



October 18, 2021
39.52398181N 107.65929467W

Photo 1: Photos show unused bags of “insulation snakes” improperly stored on the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 311696



Photo 2: Photos taken from the cut slopes of the Location. Photos provide examples showing that control measures to protect and stabilize the slopes of the Location are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 311696



Photo 3: Photos taken from the cut slopes of the Location. Photos provide examples showing that control measures to protect and stabilize the slopes of the Location are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 311696



Photo 4: Photos taken from the slopes on the west end of the Location. Photos provide examples showing that control measures to protect and stabilize the slopes of the Location are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 311696



Photo 5: Photo shows example of anchors observed that have not been properly marked, or markers are in disrepair. Marker maintenance is an ongoing issue that has been documented in previous inspections; markers appear to be frequently traveled over by vehicle equipment.