

TEP
Frie A
Location # 417777



location



location



TEP
Frie A
Location # 417777



Follow up inspection of cut slope



Follow up inspection of cut slope



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Frie A
Location # 417777




Previous inspection of cut slope



Previous inspection of cut slope



TEP
Frie A
Location # 417777



Follow up inspection of wildlife boards



Follow up inspection of wildlife boards

TEP
Frie A
Location # 417777



Previous inspection of wildlife boards



Previous inspection of wildlife boards



TEP
Frie A
Location # 417777



Previous inspection of labels




Follow up inspection, tank label has wrong operator and quantity is too small to read at distance



TEP
Frie A
Location # 417777



Tank label has wrong operator, quantity, etc.



Lack of bull plug/cap



TEP
Frie A
Location # 417777



Lack of bull plug/cap



Lack of bull plug/cap



TEP
Frie A
Location # 417777



Lack of stabilization/compaction



Lack of stabilization/compaction



TEP
Frie A
Location # 417777



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
Frie A
Location # 417777



Lack of stabilization/compaction



Lack of stabilization/compaction

