

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /20-11 (PN20)

Location ID: 334682



Photo #5114 from entrance to location.



Photo #5115 from entrance to location.





## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /20-11 (PN20)

Location ID: 334682



**Photo #5116 No battery sign located at the tank battery.**



**Photo #5117 Glycol storage tank missing required information.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources