

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 1 – Pumping Unit



Photo 2 – Gas Engine House

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 3 – Stained Soil and Mechanical Conditions. Oily Waste



Photo 4 – Flare and ECD

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 5 – Heater Treater



Photo 6 – Gas Meter House

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 7 – Tank Battery Sign



Photo 8 – Tank Battery