

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971




Photo 1 loc pic and cattle guard



Photo 2 Tracking pad cattle guard not properly maintained full of sediment.

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971



Photo 3 Trash and unused mechanical issue, electric panel has no meter.



Photo 4 new well head sign not properly installed laying on the ground.

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971



Photo 5 Land owner installed electric fence to keep livestock out of open excavation.



Photo 6 loc pic

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971



Photo 7 loc pic



Photo 8 Trash piping removed from excavation.

Inspection Photos
Location Name: Hladky- O’Gorman #3
Location ID: 332971



Photo 9 improper BMP’s around open excavation. Improper fencing of open excavation.




Photo 10 improper BMP’s around open excavation. Improper fencing of open excavation.

Inspection Photos
Location Name: Hladky- O’Gorman #3
Location ID: 332971



Photo 11 improper BPM’s sediment not being contained and leaving location onto adjacent field. Arrow is electric fence.



Photo 12 open excavation.

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971



Photo 13 Debris and sediment leaving location from excavated area.



Photo 14 inadequate berm around crude oil tanks.

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971



Photo 15 inadequate berm around crude oil tanks sediment leaving location.



Photo 16 What appears to be contaminated soil on compromised liner with no BMP's

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971



Photo 17 No BMP's around contaminated soil pile



Photo 18 No BMP's around contaminated soil pile

Inspection Photos
Location Name: Hladky- O’Gorman #3
Location ID: 332971



**Photo 19 No BMP's around contaminated soil pile surface
water is approx 5FT for unprotected pile.**



**Photo 20 not fencing around contaminated pile to keep livestock
from spreading material on location and into waterway,**

Inspection Photos
Location Name: Hladky- O'Gorman #3
Location ID: 332971



Photo 21 loc pic



Photo 22 loc pic