

**Inspection Photos**  
**Location Name: Farm Ranch Exploration 1**  
**Location ID: 319972**



**Photo #1 Tanks and weeds.**

**Photo #2 Tanks and weeds.**

Inspection Photos  
Location Name: Farm Ranch Exploration 1  
Location ID: 319972



Photo #3 separator and weeds.



Photo #4 separator and weeds.

Inspection Photos  
Location Name: Farm Ranch Exploration 1  
Location ID: 319972



Photo #5 stained soil around separator.



Photo #6 ECD and weeds .

Inspection Photos  
Location Name: Farm Ranch Exploration 1  
Location ID: 319972



**Photo #7 weeds laid up against the lit and burning ECD.**

**Photo #8 Pump Jack.**