

Inspection Photos
Location Name: Nielson #5
API: 05-007-06141



Nielson #5 location photo. 300 bbl AST is in the background.



Nielson #5 pump jack and well head.

Inspection Photos
Location Name: Nielson #5
API: 05-007-06141



Uncompacted earthen berm around AST.



Uncompacted earthen berm does not appear to be sufficiently impervious to adequately contain releases.