

Inspection Photos

API: 043-06216

API: 043-06221

Operator: AUSCO PETROLEUM INC

Inspection Date: 10/27/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 1. Facing southwest along the access road. Stormwater from the road is creating erosion in area shown at red arrow. The wattles placed in this area are displaced and are not controlling erosion. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 2. Facing southwest toward the location. There is trailers and machinery park close to the well head. Storage of equipment, vehicle, trailers, supplies not necessary for use on the location is prohibited.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 3. Facing southwest at the location. Gravel has been hauled in to this area of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 4. Facing south at location. This area has been disturbed from recent activities.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 5. There is equipment storage at the south side of the location which has disturbed vegetation. Storage of equipment, vehicle, trailers, supplies not necessary for use on the location is prohibited.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 6. There was trash debris beginning to blow off site which came from the storage of equipment shown in previous photo. There are also numerous undesirable weeds (Russian thistle) which are now debris and need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 7. Facing northwest toward the location. The degraded wattles remain in this area and erosion has not been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 8. Facing toward the southwest side of the location. The wattles remain displaced and there is erosion along this area which is not stabilized. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 9. There is erosion along the cut slope which has not been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 10. There is oil leaking from the pumpjack engine. There is also oil stained soil on the ground. Stained soil have not been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 11. There is storage of supplies at the tank battery.



Photo 12. There is stained soil at the outlet of the PW tank which has not been cleaned up. There is also unused pipe storage at the base of the berm.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 13. The top perimeter ditch is directing stormwater toward the road which has deposited sediment onto the road. BMP's are needed in this area. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021

Inspection Photos



Photo 14. There is erosion occurring across the road at the north side of the location caused by stormwater directed from the top perimeter ditch shown in the previous photo. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc ID: 429093 | Date: 10/27/2021