

**Inspection Photos**  
**Location Name: Albert Martinez #1**  
**API: 05-007-06253**



**Albert Martinez #1 pump jack and well head.**



**Albert Martinez #1 location photo. Pile of vegetative debris in foreground.**



**Inspection Photos**  
**Location Name: Albert Martinez #1**  
**API: 05-007-06253**



**Oil staining near flow line elbow.**



**Albert Martinez #1 well head sign. Additional information recently added to sign has fallen down.**



**Inspection Photos**  
**Location Name: Albert Martinez #1**  
**API: 05-007-06253**



**Domestic Tap #477321.**



**Domestic tap #477321. Pressure gauge reads approximately 14 psi.**



**Inspection Photos**  
**Location Name: Albert Martinez #1**  
**API: 05-007-06253**



**Albert Martinez #1 tank battery. Uncompacted earthen berm shared with Nielson #4 AST.**



**ASTs have been attached to anchors.**