

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2021

Submitted Date:

10/30/2021

Document Number:

696105185**FIELD INSPECTION FORM**
 Loc ID 455352 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455346	WELL	XX	06/09/2018		123-46999	SLW RANCH STATE BB06-662	ND
455347	WELL	XX	06/09/2018		123-47000	SLW RANCH STATE BB06-682	ND
455348	WELL	XX	06/09/2018		123-47001	SLW RANCH STATE BB06-672	ND
455349	WELL	XX	06/09/2018		123-47002	SLW RANCH STATE BB06-642	ND
455350	WELL	XX	06/09/2018		123-47003	SLW RANCH STATE BB06-631	ND
455351	WELL	XX	06/09/2018		123-47004	SLW RANCH STATE BB06-652	ND
455354	WELL	XX	06/09/2018		123-47005	SLW RANCH STATE BB06-619	ND

General Comment:

This is an APPROVED PERMIT TO DRILL inspection.

Well(s): 7: Approved Permit To Drill | XX.

Originally permitted as 7-well pad.

7: Approved Permits to Drill: STATUS: Expired. Not drilled.

No disturbance or evidence of oil & gas activity.

Approved Permits to Drill (EXPIRED) Location GPS coordinates:

From North to South:

1.) SLW Ranch State BB06-682: 40.429180 / -104.487910

2.) SLW Ranch State BB06-672: 40.429110 / -104.487910

3.) SLW Ranch State BB06-662: 40.429050 / -104.487910

4.) SLW Ranch State BB06-652: 40.428990 / -104.487910

5.) SLW Ranch State BB06-642: 40.428930 / -104.487910

6.) SLW Ranch State BB06-631: 40.428870 / -104.487910

7.) SLW Ranch State BB06-619: 40.428800 / -104.487910

Inspected Facilities

Facility ID: <u>455346</u>	Type: <u>WELL</u>	API Number: <u>123-46999</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>455347</u>	Type: <u>WELL</u>	API Number: <u>123-47000</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>455348</u>	Type: <u>WELL</u>	API Number: <u>123-47001</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>455349</u>	Type: <u>WELL</u>	API Number: <u>123-47002</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>455350</u>	Type: <u>WELL</u>	API Number: <u>123-47003</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>455351</u>	Type: <u>WELL</u>	API Number: <u>123-47004</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>455354</u>	Type: <u>WELL</u>	API Number: <u>123-47005</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 10/28/2021 at approximately 17:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: BB /06-32 PAD Location ID: 455352 Well Name(s): SLW Ranch State BB06-662, SLW Ranch State BB06-682, SLW Ranch State BB06-672, SLW Ranch State BB06-642, SLW Ranch State BB06-631, SLW Ranch State BB06-652, SLW Ranch State BB06-619. API: 05-123-46999, 05-123-47000, 05-123-47001, 05-123-47002, 05-123-47003, 05-123-47004, 05-123-47005. Location County: Weld County, Colorado Weather: Mostly Sunny, dry. While there, I observed:</p> <p>Well(s): 7: Approved Permit To Drill XX. Originally permitted as 7-well pad. 7: Approved Permits to Drill: STATUS: Expired. Not drilled. No disturbance or evidence of oil & gas activity.</p> <p>Approved Permits to Drill (EXPIRED) Location GPS coordinates: From North to South: 1.) SLW Ranch State BB06-682: 40.429180 / -104.487910 2.) SLW Ranch State BB06-672: 40.429110 / -104.487910 3.) SLW Ranch State BB06-662: 40.429050 / -104.487910 4.) SLW Ranch State BB06-652: 40.428990 / -104.487910 5.) SLW Ranch State BB06-642: 40.428930 / -104.487910 6.) SLW Ranch State BB06-631: 40.428870 / -104.487910 7.) SLW Ranch State BB06-619: 40.428800 / -104.487910</p> <p>APPROVED PERMIT TO DRILL STATUS Comments: 1.) Form 2 Application for Permit-to-Drill on file. Expiration Date: 06/08/2020. Approved. Well API Number 05-123-46999 has not been drilled. 2.) Form 2 Application for Permit-to-Drill on file. Expiration Date: 06/08/2020. Approved. Well API Number 05-123-47000 has not been drilled. 3.) Form 2 Application for Permit-to-Drill on file. Expiration Date: 06/08/2020. Approved. Well API Number 05-123-47001 has not been drilled. 4.) Form 2 Application for Permit-to-Drill on file. Expiration Date: 06/08/2020. Approved. Well API Number 05-123-47002 has not been drilled. 5.) Form 2 Application for Permit-to-Drill on file. Expiration Date: 06/08/2020. Approved. Well API Number 05-123-47003 has not been drilled. 6.) Form 2 Application for Permit-to-Drill on file. Expiration Date: 06/08/2020. Approved. Well API Number 05-123-47004 has not been drilled. 7.) Form 2 Application for Permit-to-Drill on file. Expiration Date: 06/08/2020. Approved. Well API Number 05-123-47005 has not been drilled.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/30/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105187	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5568637