

Inspection Photos  
Location Name: Champlin 248 Amoco A3  
Location ID: 320030



Photo #1 Tanks.



Photo #2 Separator.

Inspection Photos  
Location Name: Champlin 248 Amoco A3  
Location ID: 320030




Photo #3 Pump Jack.



Photo #4 Stained soil on the back side of crude tanks

**Inspection Photos**  
**Location Name: Champlin 248 Amoco A3**  
**Location ID: 320030**



**Photo #5 Stained soil on the back side of crude tanks.**