

Inspection Photos
Location Name: Bashor 18-1
Location ID: 323023





Photo 1 – Wellhead – Weeds

Photo 2 – Unmarked 1" Riser and Stained Soil

Inspection Photos
Location Name: Bashor 18-1
Location ID: 323023



Photo 3 – Marking is fading



Photo 4 – Marking has faded

Inspection Photos
Location Name: Bashor 18-1
Location ID: 323023



Photo 5 – Pumping Unit

Photo 6 – Tank Battery

Inspection Photos
Location Name: Bashor 18-1
Location ID: 323023



Colorado Oil and Gas Conservation Commission
40.75058, -104.14303, 4924.1ft, 322°
10/12/2021 13:56:59



CLARK BASHOR 18-1
SW NW 18-9N-60W
WELD COUNTY, COLORADO
BISON
OIL & GAS II
24 HOURS CONTACT: 303-441-2844
LOCAL EMERGENCY SERVICES: 911
Directions: WCR 110 and WCR 390, SE on 390 for 1 mile, turn S 1/2 mile, then E

SMITH ENERGY CORP.
PO BOX 5172 • GREELEY CO. • 970-330-7034
CLARK BASHOR 18-1
SW NW-18-9N-60W
Weld County, Colo.

Colorado Oil and Gas Conservation Commission
40.75067, -104.14333, 4923.8ft, 83°
10/12/2021 13:58:00

Photo 7 – Heater Treater

Photo 8 – Tank Battery Sign