

Inspection Photos  
Location Name: Bashor 18-1  
Location ID: 323023



**Photo 1 – Wellhead – Weeds**



**Photo 2 – Stained Soil**

Inspection Photos  
Location Name: Bashor 18-1  
Location ID: 323023



**Photo 3 – Unmarked 1” Riser – Marked ‘Fuel Gas’**



Inspection Photos  
Location Name: Bashor 18-1  
Location ID: 323023



**Photo 4 – Marked 'Recirc'**



**Photo 5 – Marked 'Recirc'**