

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2021

Submitted Date:

10/22/2021

Document Number:

689806545

**FIELD INSPECTION FORM**Loc ID 438250 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION &amp; PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Boyer, David	303-994-0000	david@d90energy.com	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438251	WELL	DG	04/10/2017	LO	057-06530	Ray Ranch 0780 4-16H	SI
438252	WELL	PR	03/01/2019	OW	057-06531	Ray Ranch 0780 #1-16H	PR
446363	WELL	PR	08/01/2020	OW	057-06554	Ray Ranch 0780 2-16H	PR
446364	WELL	DG	08/06/2016	OW	057-06555	Ray Ranch 0780 3-16H	SI

**General Comment:**

Routine FIU follow up inspection. Follow up to inspection from 3/30/2021 document number 689805591. Form 9 to transfer from Sandridge to D90 received 5/12/2021 document number 402676753, form remains In Process.

Stained soil has been removed.

Emergency contact number has been added to location signs.

Battery and Wellhead signs have been updated to reflect current operator but remain out of compliance with updated sign rules, 605.

Because of this, sign related corrective actions remain outstanding. It is suggested that operator read the comments in this and previous inspections in addition to reading the rules, so that signs can be updated to be in compliance.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/12/2021
Type	WELLHEAD		
Comment:	Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/12/2021

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Generator		
Corrective Action:		Date:	
Type: Horizontal Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	



**Inspected Facilities**Facility ID: 438251 Type: WELL API Number: 057-06530 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last MIT 12/10/2018

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 438252 Type: WELL API Number: 057-06531 Status: PR Insp. Status: PR**Producing Well**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 446363 Type: WELL API Number: 057-06554 Status: PR Insp. Status: PR**Producing Well**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 446364 Type: WELL API Number: 057-06555 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last MIT 12/10/2018

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Gravel						
Compaction						
		Gravel				
Berms						

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT