

Final Reclamation Inspection

October 21st, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323335

Inspection Document #: 701900225

Weld County, CO

NWSE Section 10 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Purvis 10-1
Location ID: 323335



Photo 1. 2020 aerial imagery of the well pad and tank battery. Note: the tank battery and well pad shared a disturbance pad.

Inspection Photos
Location Name: Purvis 10-1
Location ID: 323335



Photo 2. Overview photo of the well pad and tank battery. Photo shows that the disturbance pad has been harvested and will need to be re-inspected during the next growing season.