

Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335647

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335647



Photo 1: Photos 1-2 taken from the southwest end of the Location. Photos provide an overview of the Location from northeast, east to south. Photos also show interim reclamation of areas not needed for production has not been conducted in accordance with 1003 rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335647



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335647



Photo 3: Photos taken from the Location entrance, facing west and north. Access road/entrance in photo left was required to be reclaimed as part of 1003 interim reclamation; photo shows interim reclamation of the Location has not been performed in accordance with 1003 rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335647



Photo 4: Photos provide examples of the slopes of the Location. Stormwater and erosion control measures to stabilize and protect the slopes, and to allow for sediment laden-free stormwater discharge remain missing or insufficient.