

Inspection Photos
Location Name: Shahan (OWP) #2
API: 05-007-05170



Shahan (OWP) #2 location photo.



Shahan (OWP) #2 well head.

Inspection Photos
Location Name: Shahan (OWP) #2
API: 05-007-05170



Reference photo from site visit on 4/9/21.



Soil has been removed from around well. Pool of stagnant water present during this inspection.