

Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335815

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 1: Photos 1-2 taken from the northeast end of the Location. Photos provide an overview of the Location from south, southwest, to west. Photos also show interim reclamation of areas not needed for production has been performed or is in process.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335815



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 3: Photos provides example showing interim reclamation of areas not needed is in process.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 4: Photos taken from the north end of the location. Photo shows example of areas on the north end of the Location where erosion control measures to stabilize the soils are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 5. Photos taken from the production area and provide examples showing control measures to stabilize the Location, and mitigate tracking and offsite sediment transport are missing or insufficient.