

# Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335889

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 335889



**Photo 1:** Photo taken from the Location, facing north. Photo shows large areas where control measures to protect and stabilize the cut slope remains missing or insufficient. Photo also shows section of erosion control blanket that has not been maintained in proper functioning condition.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 335889



**Photo 2:** Photo shows large areas where control measures to protect and stabilize the cut slope remains missing or insufficient; erosion degradation evident.



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335889



**Photo 3:** Photo shows large areas where control measures to protect and stabilize the cut slope remains missing or insufficient; erosion degradation evident.