

Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 324288

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324288



Photo 1: Photos 1-2 provide an overview of the Location from west, northwest to northeast.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324288



November 1, 2021
39.52668819N 108.22856045W

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324288



Photo 3: Photos taken from the production area and provide examples showing control measures to stabilize the Location, and mitigate tracking and offsite sediment transport are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324288



Photo 4: Photo taken from the east end of the location. Photo shows Operator has implemented erosion blankets on the bare slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324288



Photo 5: Photo taken from the east end of the Pond G. Photo shows gate has been left open; Best Management Practices to prevent access to the Pond G inadequate.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324288



Photo 6: Photo shows netting at the Pond G has been removed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324288



Photo 7: Continued from Photo 5. Photo shows Reclamation Specialist closed and secured gate and access to the Pond G on behalf of the Operator.