

Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335643

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335643



November 1, 2021
39.52368192N 108.22558589W



November 1, 2021
39.52386977N 108.22509238W

Photo 1: Photos provide example showing control measures to protect/stabilize the cut slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335643



Photo 2: Photos provide examples showing controle measures to protect/stabilize the fill slopes, and to manage runoff from the Location remain missing or insufficient. Photo right show fill material from the slopes covering vegetation at the toe of the slope.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335643



November 1, 2021
39.52348526N 108.2257954W



November 1, 2021
39.1848759N 108.2807172W

Photo 3: Photos provide examples of the interim areas. Unable to find evidence that additional reclamation work has been conducted at this time.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335643



Photo 4: Photo taken from the northeast end of the Location. Photo show the only interim areas of the Location where topsoil appears to have been replaced. Amount of topsoil observed does not appear sufficient in quantity for final reclamation.