

Inspection Photos

11/01/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335950

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335950



Photo 1: Photos taken from the gully erosion observed on the north end of the Location. Photos provide examples showing control measures to allow for proper stormwater discharge, and minimize erosion degradation remain missing or insufficient per good engineering practices.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335950



Photo 2: Photos taken from the gulley erosion north of the Location. Photos show operator has implemented erosion log in addition to the rock socks within the areas of erosion. Work to address the gulley erosion inadequate; velocity checks alone insufficient to manage runoff from the Location, to allow for proper stormwater discharge, and to minimize erosion degradation per good engineering practices. Photos also provide example of additional erosion degradation and sediment transport evident at the gulley.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335950



Photo 3: Photos taken from the gulley erosion north of the Location. Photos show operator has implemented erosion log in addition to the rock socks within the areas of erosion. Work to address the gulley erosion inadequate; velocity checks alone insufficient to manage runoff from the Location, to allow for proper stormwater discharge, and to minimize erosion degradation per good engineering practices. Photos also provide example of additional erosion degradation and sediment transport evident at the gulley.