

Inspection Photos

API: 071-08046

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/3/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 11/3/2021

Inspection Photos



Photo 1. Facing southeast along the access road. The culvert along the road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 11/3/2021

Inspection Photos



Photo 2. Facing west toward the access road near the location. There is erosion along the road which needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 11/3/2021

Inspection Photos



Photo 3. Facing west along the access road at the location. There was disturbance that has occurred in this area which needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 11/3/2021

Inspection Photos



Photo 4. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 11/3/2021