

# Interim Reclamation Inspection

November 2, 2021

Operator: RENEGADE OIL & GAS COMPANY LLC - #74165

Location ID: 401324

Inspection Document #: 697503467

Washington County, CO

NWNW Section 2 T1N R54W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HORN #2-4  
Location ID: 401324



**Photo 1.** Photo taken from the well location, facing East. Photo illustrates the well location meets Rule 1004 standards.







**Photo 2.** Photo illustrates 1 of 5 guy line anchors that have not been removed.



Inspection Photos  
Location Name: HORN #2-4  
Location ID: 401324



**Photo 3.** Photo taken from the well location, facing South. Photo illustrates the lease road is still in use for other nearby wells.



**Photo 4.** Photo taken from the well location, facing North. Photo illustrates the tank battery is still in use for other nearby wells.



Inspection Photos  
Location Name: HORN #2-4  
Location ID: 401324



**Photo 5.** Photo illustrates an active flowline riser based on previous inspections.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697503467