

Mull Drilling Company INC, BSR A 1-19
073-06779

Inspection 688311498

11/2/2021

Wildlife Netting Inspection/DA



Well is cut,
capped and
covered.

Colorado Oil and Gas Conservation Commission
38.99101, -103.37752, 4872.0ft, 27°
11/02/2021 03:43:19 PM




Colorado Oil and Gas Conservation Commission

38.9906, -103.37734, 4839.2ft, 273°

11/02/2021 03:42:11 PM



Colorado Oil and Gas Conservation Commission
38.99068, -103.37755, 4862.2ft, 235°
11/02/2021 03:42:35 PM



Colorado Oil and Gas Conservation Commission
38.99076, -103.37763, 4858.9ft, 233°
11/02/2021 03:42:51 PM



Colorado Oil and Gas Conservation Commission
38.99081, -103.37777, 4865.5ft, 152°
11/02/2021 03:43:56 PM



Colorado Oil and Gas Conservation Commission
38.9908, -103.37778, 4872.0ft, 183°
11/02/2021 03:44:02 PM



Colorado Oil and Gas Conservation Commission

38.99055, -103.37788, 4875.3ft, 68°

11/02/2021 03:44:37 PM



Colorado Oil and Gas Conservation Commission
38.99055, -103.37788, 4878.6ft, 92°
11/02/2021 03:44:40 PM