

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2021

Submitted Date:

10/28/2021

Document Number:

701102120

**FIELD INSPECTION FORM**
 Loc ID: 334500 Inspector Name: LONGWORTH, MIKE On-Site Inspection: ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1001 17TH STREET #1900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288108	WELL	PR	08/26/2015	GW	077-09189	DAVID 23-5	PR
288109	WELL	PR	03/01/2019	GW	077-09188	DAVID 23-7	PR
288110	WELL	PR	01/06/2009	GW	077-09187	DAVID 23-10	PR
288111	WELL	PR	03/01/2017	GW	077-09186	DAVID 23-11	PR
288112	WELL	PR	03/17/2009	GW	077-09185	DAVID 23-2	PR
288113	WELL	PR	03/01/2017	GW	077-09184	DAVID 23-6	PR
288215	WELL	PR	09/01/2018	GW	077-09207	DAVID FED. 23-15	PR
288216	WELL	PR	03/01/2017	GW	077-09206	DAVID 23-12	PR
288217	WELL	PR	03/01/2017	GW	077-09205	DAVID 23-9	PR
288218	WELL	PR	07/01/2021	GW	077-09204	DAVID 23-8	PR
288219	WELL	PR	05/09/2008	GW	077-09203	DAVID 23-1	PR
293585	WELL	PR	08/26/2015	GW	077-09453	DAVID 23-7C	PR
293586	WELL	PR	01/19/2010	GW	077-09454	DAVID 23-7B	PR
293587	WELL	PR	04/01/2018	GW	077-09455	DAVID 23-7A	PR

**General Comment:**

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

No labeling on separator glycol tanks.

3- 4 unit vertical heated separators with glycol vessel approximately 72"x48"x159". Approximately 56.6 bbls

1- 5 unit vertical heated separator with a similar but larger capacity.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	No labeling on separator glycol tanks. 3- 4 unit vertical heated separators with glycol vessel approximately 72"x48"x159". Approximately 56.6 bbls 1- 5 unit vertical heated separator with a similar but larger capacity.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 01/31/2022
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors	# 4		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 14		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	1000 gallons	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	7	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
--------	----	--	--

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	288108	Type:	WELL	API Number:	077-09189	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288109	Type:	WELL	API Number:	077-09188	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288110	Type:	WELL	API Number:	077-09187	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288111	Type:	WELL	API Number:	077-09186	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288112	Type:	WELL	API Number:	077-09185	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288113	Type:	WELL	API Number:	077-09184	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288215	Type:	WELL	API Number:	077-09207	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288216	Type:	WELL	API Number:	077-09206	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 288217	Type: WELL	API Number: 077-09205	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288218	Type: WELL	API Number: 077-09204	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288219	Type: WELL	API Number: 077-09203	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 293585	Type: WELL	API Number: 077-09453	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 293586	Type: WELL	API Number: 077-09454	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 293587	Type: WELL	API Number: 077-09455	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
		Compaction				
Gravel						
Berms						
Ditches						
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402858773	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569149</a>
701102121	Inspection 701102120 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569146">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569146</a>