

Inspection Photos
Location Name: Community #1
Location ID: 319888



Photo 1 loc pic. Tracking pad and Dead weeds along road and on location.



Photo 2 TNK BTRY

Inspection Photos
Location Name: Community #1
Location ID: 319888



Photo 3 ECD



Photo 4 Dead man and dead weeds on location

Inspection Photos
Location Name: Community #1
Location ID: 319888



Photo 5 Dead man and dead weeds on location.



Photo 6 Well head.