

KP Kauffman - COGCC Inspection Photos
Location: Nessu Constolidation OLF Release
Spill ID # 476987 Date 11/04/2021



View of slight bowing at the southern tie-in with stub end. There is no embedment into soil.



View of new fiberglass replacement section supported by angular rock on top of screw-type pipe support. In lieu of embedment into backfill.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

KP Kauffman - COGCC Inspection Photos
Location: Nessu Constolidation OLF Release
Spill ID # 476987 Date 11/04/2021



View of west edge of larger excavation area containing improperly abandoned lines. Red arrow is partial exposure of one of the two lines in question.



View of two improperly abandoned lines. Pink and blue arrows appear to be two split ends of the same line as both are visibly open-ended.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources