

Inspection Photos

11/05/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334283

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334283



Photo 1: Photo shows erosion degradation at the fill slope; photo shows stormwater and erosion control measures remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334283



Photo 2: Photo shows erosion degradation at the fill slope; photo shows stormwater and erosion control measures remain missing or insufficient.