

Inspection Photos

11/05/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 311604

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 311604



Photo 1: Photo 1-2 taken from the production areas of the Location and provide examples showing control measures to stabilize the production areas of the Location, and to mitigate tracking and offsite sediment transport remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 311604



Photo 2: See comments under photo 1.