

Inspection Photos

API: 071-09879

Operator: OGRIS OPERATING LLC

Inspection Date: 11/8/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 11/8/2021

Inspection Photos



Photo 1. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 11/8/2021

Inspection Photos



Photo 2. The berm around the tank has been repaired.



Inspection Photos



Photo 3. Facing west at the location. The soils are bare of vegetation at the southwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 11/8/2021

Inspection Photos



Photo 4. The soils are bare of vegetation at the southwest side. This area needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 11/8/2021