

Inspection Photos
Location Name: Ross-Government-USA 43-7
Location ID: 312938



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. No bradenhead access apparent.



Inspection Photos
Location Name: Ross-Government-USA 43-7
Location ID: 312938



Photo 3. Pit on location with no permit.



Photo 4. Tubing stored on location. Debris on location.

