

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 1. Overview of location taken facing southwest.



Photo 2. Overview of location taken facing southwest.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 3. Wellhead sign knocked over.



Photo 4. Site degradation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 5. Missing and incomplete tank labels.



Photo 6. Missing and incomplete tank labels.

