

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 1. Overview of location taken facing southeast.



Photo 2. Equipment stored on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 3. Equipment stored on location.



Photo 4. Equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 5. Equipment stored on location.



Photo 6. Equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 7. Equipment stored on location.



Photo 8. Equipment stored on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 9. Equipment stored on location.



Photo 10. Equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 11. Equipment stored on location.



Photo 12. No wellhead sign. No bradenhead access apparent.

