

Inspection Photos
Location Name: McCallum Unit 87
Location ID: 324653



Photo 1. Overview of location taken facing northwest.



Photo 2. No bradenhead access apparent.