

S&D LLC, Kissler Dan 2-10  
005-06864  
Inspection #688311525  
11/10/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission  
39.71224, -104.54517, 5567.6ft, 271°  
11/10/2021 08:43:38 AM




Colorado Oil and Gas Conservation Commission  
39.71222, -104.54588, 5577.4ft, 74°  
11/10/2021 08:38:08 AM






Colorado Oil and Gas Conservation Commission  
39.71226, -104.5456, 5544.6ft, 64"  
11/10/2021 08:42:56 AM



A photograph showing a close-up view of a dirt and gravel surface. The ground is uneven, with various shades of brown and grey. There are some small, dry plant stems and debris scattered across the surface. At the bottom center, the tip of a dark-colored boot is visible, suggesting the person is standing on the ground. The text is overlaid in the bottom right corner.

Colorado Oil and Gas Conservation Commission  
39.71228, -104.54558, 5547.9ft, 48°  
11/10/2021 08:42:59 AM





Colorado Oil and Gas Conservation Commission  
39.71222, -104.54448, 5547.9ft, 61°  
11/10/2021 08:39:43 AM