

Inspection Photos
Location Name: Carl R Deepe C Battery
Location ID: 475687



Photo 1 TB sign

Photo 2 TB placards are peeling and need to be replaced

Inspection Photos
Location Name: Carl R Deepe C Battery
Location ID: 475687



Photo 3 Gas Meter Run

Photo 4 card in meter house indicates calibration is not current

Inspection Photos
Location Name: Carl R Deepe C Battery
Location ID: 475687



Photo 5 flow line manifold

Photo 6 Horiz. Heated Sep.