

Inspection Photos
Location Name: Carlson #1
Location ID: 319790



Photo 1 Well head



Photo 2 loc pic

Inspection Photos
Location Name: Carlson #1
Location ID: 319790



Photo 3 riser not LOTO



Photo 4 loc pic

Inspection Photos
Location Name: Carlson #1
Location ID: 319790



Colorado Oil and Gas Conservation Commission
39.91279, -104.73566, 1582.0m
Nov 16, 2021 9:58:44 AM



Colorado Oil and Gas Conservation Commission
39.91255, -104.73566, 1580.0m
Nov 16, 2021 9:59:22 AM

Photo 5 Trash on locaiton

Photo 6 TNK BTRY

Inspection Photos
Location Name: Carlson #1
Location ID: 319790



Photo 7 Stained soil around crude oil tank.

Photo 8 produced water tank

Inspection Photos
Location Name: Carlson #1
Location ID: 319790



Photo 9 loc pic TRASH



Photo 10 loc pic TRASH

Inspection Photos
Location Name: Carlson #1
Location ID: 319790



Photo 11 loc pic

Photo 12 loc pic TRASH.